Declassification Review by NGA/DoD

0UT-52220

•	4	~	•	Ε,	T	カモ	15	4 ØZ
⋾	L	U	π	E.	ı	עש	ょっ	406

1933 NOV 5

5 NOV 196325X1

CAMERA B 7 WAS USED IN MISSION 3763 FLOWN ON 31 OCTOBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

HFS					
CTC	A				

- 2. ORIGINAL NEGATIVE:
  - THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

- 9R SIDE: THERE IS A SLIGHT INBOARD EDGE FOG ALONG THE PMS FIRST 50 FRAMES. A MANUFACTURER'S SPLICE APPEARS IN FRAME 41 ACL AND HEAT SPLICES ARE PRESENT IN FRAMES 267, 1359, 1405, AND 1499. PINHOLES AND BLISTERS ARE NOTED IN FRAMES 273, 438 AND 2307. Grace (File) THERE ARE CRIMPS AND HANDLING MARKS IN FRAME 1359 AND 1597. A PIECE OF FOREIGN MATTER IS ADHERED TO THE EMULSION IN FRAME 1463 AND THERE ARE MINOR SCRATCHES IN FRAME 1499.
- 9L SIDE: THERE IS A SERIES OF MINUS DENSITY DOTS 2.0" FROM THE OUTBOARD EDGE SPACED 1.55" APART THROUGHOUT THE MISSION. DIRT IS NOTED IN FRAME 1863 AND BLISTERS ARE PRESENT IN FRAMES 838. 1518. AND 2053. THERE IS A CHEMICAL MARK IN FRAME 1928.
- D. BOTH SIDES: THERE WERE NO CAMERA MALFUNCTIONS DURING THIS MISSION. FRAMES 1 THROUGH 942 ON THE 9L SIDE CONTAIN BASE SCRATCHES AND FRAMES 1359 THROUGH 2364 ON THE 9R SIDE CONTAIN SIMILAR SCRATCHES WHICH HAVE BEEN DETERMINED TO HAVE OCCURRED AT THE PROCESSING SITE. THERE WERE 2364 EXPOSURES IN THIS MISSION.

## POSTIVE:

- THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE POSITIVES ARE GOOD.
- CLOUDS COVERED 20 PERCENT OF THE MISSION. SECRET

GROUP 1 Excluded from automati downgrading and

25X1

END OF MESSAGE